



CUSTOMER OPERATIONS  
160 RIO ROBLES  
SAN JOSE, CA 95134

PDN #: M000995N

DATE: 21-May-2020

## PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Discontinuance	DS28E01P-BOS+	N/A	16-May-2021	12-Nov-2021	Part can no longer be manufactured
Discontinuance	DS28E01P-BOS+T	N/A	16-May-2021	12-Nov-2021	Part can no longer be manufactured
Discontinuance	DS28E01P-W0G+1T	N/A	16-May-2021	12-Nov-2021	Part can no longer be manufactured
Discontinuance	DS28E01P-W0M+1	N/A	16-May-2021	12-Nov-2021	Part can no longer be manufactured
Discontinuance	DS28E01P-W0M+1T	N/A	16-May-2021	12-Nov-2021	Part can no longer be manufactured
Discontinuance	DS28E01P-W0S+1T	N/A	16-May-2021	12-Nov-2021	Part can no longer be manufactured
Discontinuance	DS28E02P-W10+2	N/A	16-May-2021	12-Nov-2021	Part can no longer be manufactured
Discontinuance	DS28E02P-W10+2T	N/A	16-May-2021	12-Nov-2021	Part can no longer be manufactured
Discontinuance	DS28E02P-W10+6	N/A	16-May-2021	12-Nov-2021	Part can no longer be manufactured
Discontinuance	DS28E02P-W10+6T	N/A	16-May-2021	12-Nov-2021	Part can no longer be manufactured
Discontinuance	DS28E02P-W10+9	N/A	16-May-2021	12-Nov-2021	Part can no longer be manufactured
Discontinuance	DS28E02P-W10+9T	N/A	16-May-2021	12-Nov-2021	Part can no longer be manufactured
Discontinuance	DS28E15P-04A-00+1	N/A	16-May-2021	12-Nov-2021	Part can no longer be manufactured
Discontinuance	DS28E15P-04A-00+1T	N/A	16-May-2021	12-Nov-2021	Part can no longer be manufactured
Discontinuance	DS28E22P-04A-00+1	N/A	16-May-2021	12-Nov-2021	Part can no longer be manufactured
Discontinuance	DS28E22P-04A-00+1T	N/A	16-May-2021	12-Nov-2021	Part can no longer be manufactured
Discontinuance	DSHB1Q02+	N/A	16-May-2021	12-Nov-2021	Part can no longer be manufactured
Discontinuance	DSHB1Q02+T10	N/A	16-May-2021	12-Nov-2021	Part can no longer be manufactured
Discontinuance	DSQ3301-K02+T	N/A	16-May-2021	12-Nov-2021	Part can no longer be manufactured
Discontinuance	MAX16938AUERA/V+	N/A	16-May-2021	12-Nov-2021	Part can no longer be manufactured
Discontinuance	MAX16938AUERA/V+T	N/A	16-May-2021	12-Nov-2021	Part can no longer be manufactured
Discontinuance	MAX16938AUERB/V+	N/A	16-May-2021	12-Nov-2021	Part can no longer be manufactured
Discontinuance	MAX16938AUERB/V+T	N/A	16-May-2021	12-Nov-2021	Part can no longer be manufactured
Discontinuance	MAX16938AUESA/V+	N/A	16-May-2021	12-Nov-2021	Part can no longer be manufactured
Discontinuance	MAX16938AUESA/V+T	N/A	16-May-2021	12-Nov-2021	Part can no longer be manufactured
Discontinuance	MAX16938AUESB/V+	N/A	16-May-2021	12-Nov-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 21-Jun-2020

Discontinuance	MAX16938AUESB/V+T	N/A	16-May-2021	12-Nov-2021	Part can no longer be manufactured
Discontinuance	MAX17043G-E+U	N/A	16-May-2021	12-Nov-2021	Part can no longer be manufactured
Discontinuance	MAX17415ETP+T	N/A	16-May-2021	12-Nov-2021	Part can no longer be manufactured
Discontinuance	MAX28500GSA-W21+1	N/A	16-May-2021	12-Nov-2021	Part can no longer be manufactured
Discontinuance	MAX28500GSA-W21+1T	N/A	16-May-2021	12-Nov-2021	Part can no longer be manufactured
Discontinuance	MAX5913AEMH+D	N/A	16-May-2021	12-Nov-2021	Part can no longer be manufactured
Discontinuance	MAX6075ASA25+	N/A	16-May-2021	12-Nov-2021	Part can no longer be manufactured
Discontinuance	VT231TFC-ADJ	N/A	15-Jun-2020	12-Nov-2021	Part can no longer be manufactured
Discontinuance	VT232WFCX-ADJ	MAX20710EPL+T	15-Jun-2020	12-Nov-2021	Part can no longer be manufactured
Discontinuance	VT233TFC-ADJ-001	N/A	15-Jun-2020	12-Nov-2021	Part can no longer be manufactured
Discontinuance	VT233TFCX-ADJ-001	N/A	15-Jun-2020	12-Nov-2021	Part can no longer be manufactured