

To : Dear Valued Customers

Product Discontinuance Notice

Subject : Products discontinue.																																	
Parts Affected :																																	
	<table border="1" style="width:100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 50%;">EOL</th> <th style="width: 50%;">Package</th> </tr> </thead> <tbody> <tr><td>CZRERxxxx-HF Series</td><td>0503/SOD-723F</td></tr> <tr><td>CZRER52Cxxxx-HF Series</td><td>0503/SOD-723F</td></tr> <tr><td>CDBER0140L-HF</td><td>0503/SOD-723F</td></tr> <tr><td>CDBER43-HF</td><td>0503/SOD-723F</td></tr> <tr><td>CDBER70-HF</td><td>0503/SOD-723F</td></tr> <tr><td>CDBUR0145-HF</td><td>0603/SOD-523F</td></tr> <tr><td>CDBUR0245-HF</td><td>0603/SOD-523F</td></tr> <tr><td>CDBUR0330-HF</td><td>0603/SOD-523F</td></tr> <tr><td>CDBUT0230R-HF</td><td>0603/SOD-523F</td></tr> <tr><td>CDBFR0130R-HF</td><td>1005/SOD-323F</td></tr> <tr><td>CDBFR0230L-HF</td><td>1005/SOD-323F</td></tr> <tr><td>CDBFR0245-HF</td><td>1005/SOD-323F</td></tr> <tr><td>CDBFR0530-HF</td><td>1005/SOD-323F</td></tr> <tr><td>CDSF355-B01</td><td>1005(2512)</td></tr> <tr><td>CDSF4148-B03</td><td>1005(2512)</td></tr> </tbody> </table>	EOL	Package	CZRERxxxx-HF Series	0503/SOD-723F	CZRER52Cxxxx-HF Series	0503/SOD-723F	CDBER0140L-HF	0503/SOD-723F	CDBER43-HF	0503/SOD-723F	CDBER70-HF	0503/SOD-723F	CDBUR0145-HF	0603/SOD-523F	CDBUR0245-HF	0603/SOD-523F	CDBUR0330-HF	0603/SOD-523F	CDBUT0230R-HF	0603/SOD-523F	CDBFR0130R-HF	1005/SOD-323F	CDBFR0230L-HF	1005/SOD-323F	CDBFR0245-HF	1005/SOD-323F	CDBFR0530-HF	1005/SOD-323F	CDSF355-B01	1005(2512)	CDSF4148-B03	1005(2512)
EOL	Package																																
CZRERxxxx-HF Series	0503/SOD-723F																																
CZRER52Cxxxx-HF Series	0503/SOD-723F																																
CDBER0140L-HF	0503/SOD-723F																																
CDBER43-HF	0503/SOD-723F																																
CDBER70-HF	0503/SOD-723F																																
CDBUR0145-HF	0603/SOD-523F																																
CDBUR0245-HF	0603/SOD-523F																																
CDBUR0330-HF	0603/SOD-523F																																
CDBUT0230R-HF	0603/SOD-523F																																
CDBFR0130R-HF	1005/SOD-323F																																
CDBFR0230L-HF	1005/SOD-323F																																
CDBFR0245-HF	1005/SOD-323F																																
CDBFR0530-HF	1005/SOD-323F																																
CDSF355-B01	1005(2512)																																
CDSF4148-B03	1005(2512)																																
Reason for Discontinuance :																																	
Due to low demand, these parts are discontinued.																																	
Alternative Products :																																	
Please contact sales person or manufacturer's representative.																																	
Last time buy / order entry : Oct 5, 2019																																	
Effective Date : Mar 5, 2020																																	
R&D Dept. Signature :	QA Dept. Signature :																																
																																	