



CUSTOMER OPERATIONS
 160 RIO ROBLES
 SAN JOSE, CA 95134

PDN #: M000881

DATE: 01-Dec-2018

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Lead-Free Conversion	MAX4800CXZ	MAX4800CXZ+	01-Dec-2019	01-Jun-2020	Part is leaded. Request information on lead-free version
Lead-Free Conversion	MAX4800CXZ-T	MAX4800CXZ+T	01-Dec-2019	01-Jun-2020	Part is leaded. Request information on lead-free version
Discontinuance	DS17485-3+	N/A	02-Apr-2019	01-Jun-2020	Part can no longer be manufactured
Discontinuance	DS17485-5+	N/A	02-Apr-2019	01-Jun-2020	Part can no longer be manufactured
Discontinuance	HI3-0201-5+	N/A	01-Dec-2018	01-Dec-2018	Part can no longer be manufactured
Discontinuance	MAX17073ETJ+	N/A	01-Dec-2019	01-Jun-2020	Part can no longer be manufactured
Discontinuance	MAX1881EUG+	N/A	01-Dec-2019	01-Jun-2020	Part can no longer be manufactured
Discontinuance	VT1156MFQR	N/A	01-Dec-2018	01-Dec-2018	Part can no longer be manufactured
Discontinuance	VT1156MFQX	N/A	01-Dec-2019	01-Jun-2020	Part can no longer be manufactured
Discontinuance	VT262BWFQX-ADJ	N/A	01-Dec-2019	01-Jun-2020	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 01-Jan-2019