

**To : Dear Valued Customers**

**Product Discontinuance Notice**

Subject : 1005/SOD-323F package products discontinue.																	
Parts Affected :																	
<table border="1" style="margin: auto; border-collapse: collapse;"> <thead> <tr> <th colspan="2" style="padding: 5px;">Part No.</th> </tr> </thead> <tbody> <tr> <td style="padding: 5px;">CDBF00340-HF</td> <td style="padding: 5px;">CDBF0520L-HF</td> </tr> <tr> <td style="padding: 5px;">CDBF0130R-HF</td> <td style="padding: 5px;">CDSF101A-HF</td> </tr> <tr> <td style="padding: 5px;">CDBF0140L-HF</td> <td style="padding: 5px;">CDSF101A-B05</td> </tr> <tr> <td style="padding: 5px;">CDBF0230-HF</td> <td style="padding: 5px;">CDSF4448-HF</td> </tr> <tr> <td style="padding: 5px;">CDBF0230L-HF</td> <td style="padding: 5px;">CDSFR101A-HF</td> </tr> <tr> <td style="padding: 5px;">CDBF0245-HF</td> <td style="padding: 5px;">CDSFR355B-HF</td> </tr> <tr> <td style="padding: 5px;">CDBF0320-HF</td> <td style="padding: 5px;">CDSFR4148-HF</td> </tr> </tbody> </table>		Part No.		CDBF00340-HF	CDBF0520L-HF	CDBF0130R-HF	CDSF101A-HF	CDBF0140L-HF	CDSF101A-B05	CDBF0230-HF	CDSF4448-HF	CDBF0230L-HF	CDSFR101A-HF	CDBF0245-HF	CDSFR355B-HF	CDBF0320-HF	CDSFR4148-HF
Part No.																	
CDBF00340-HF	CDBF0520L-HF																
CDBF0130R-HF	CDSF101A-HF																
CDBF0140L-HF	CDSF101A-B05																
CDBF0230-HF	CDSF4448-HF																
CDBF0230L-HF	CDSFR101A-HF																
CDBF0245-HF	CDSFR355B-HF																
CDBF0320-HF	CDSFR4148-HF																
Reason for Discontinuance :																	
Due to low demand, the part listed below will be discontinued.																	
Alternative Products :																	
Please contact sales person or manufacturer's representative.																	
Last time buy / order entry : Feb 28, 2022																	
Effective Date : Apr 30, 2022																	
R&D Dept. Signature :	QA Dept. Signature :																
																	