



## EOL Change Notification

Date: August 11, 2008

EOL Reference: EOL138

Product Reference: Various product

Dear Customer,

As always we appreciate your use of International Rectifier semiconductor products. Our commitment to customer satisfaction and continuous improvement is demonstrated by our change plans to enhance capacity, quality and reliability. This notice is to inform you of the following product discontinuance:

### Type of Change Notification:

Product discontinuance

### Reason For End-Of-Life:

Portfolio revision/update

### Products Affected:

111-3010	94-4000	IR2131C	IRFC2602B	IRG4PC60U-P
111-3011	94-4013	IR2151S	IRFC2604B	IRG4PH20K-E
111-3013	94-4018	IR2151STR	IRFC2805	IRG4PH40UD-E
111-3017	94-4019		IRFC2805TR	IRG4PSC71K
111-3021PBF	94-4023	IR3080M	IRFC2807VB	IRG4PSC71KD
111-4000	94-4043	IR3080MPBF	IRFC3504	IRG4RC10SDTRLP
111-4001	94-4084	IR3080MTR	IRFC3518B	IRG4RC10UTRL
111-4004	94-4140	IR3081AMTR	IRFC3704B	IRG4RC20FTR
111-4006	94-4283	IR3081MPBF	IRFC3711ZCB	IRG4RC20FTRL
111-5000	94-4285	IR3081MTR	IRFC3815C	IRGB30B60K
62-0067	94-4292	IR3082M	IRFC4104C	IRGB4B60K
63-6008PBF	94-4295	IR3082MTR	IRFC4104TR	IRGC100B120KC
	94-4590	IR3082MTRPBF	IRFC4310F	IRGC20B60PB
64-2045	94-4703	IR3083MPBF	IRFC5801B	IRGC4264B



# International Rectifier

41915 Business Park Drive, Temecula, California 92590 \* Telephone (951) 676-7500

64-2061PBF	94-4735	IR3084M	IRFC5851C	IRGC50B60PC
64-4001	94-4736	IR3086AM	IRFC5852C	IRGIB15B60KD1
64-4006	94-4827	IR3086AMTR	IRFC7204B	IRGP50B60PD
64-4007	94-4871	IR3086MTR	IRFC7240F	IRGS14C40LTRR
64-4008	94-4877	IR3086MTRPBF	IRFC7301B	IRGS15B60KDTRR
64-7001PBF	98-0020	IR3087MTR	IRFC7306B	IRGS4B60KD1
64-8016	98-0020TR	IR3087MTRPBF	IRFC7413ZB	IRGS4B60KD1TRR
64-8042	98-0050	IR3088M	IRFC7504B	IRGS6B60K
64-8045	98-0051	IR3088MTR	IRFC7750B	IRGS6B60KD
75-0033	98-0052	IR3092M	IRFC8104TR	IRGS6B60KDTRL
75-0046	98-0052A	IR3092MTRPBF	IRFC9120NBV	IRGS6B60KDTRR
75-0053	98-0053	IR3093MTR	IRFC9130NBV	IRGS8B60KTRL
85-0051	98-0057	IR4007K	IRFCZ48ZD	IRGSL14C40L
87-4532	98-0058	IR4428STR	IRFIB3315	IRGSL15B60KD
87-4545	98-0100	IR51H224	IRFL4315TR	IRGSL6B60KD
92-0059	98-0104	IR51H310	IRFR1205TRL	IRGSL6B60KPBF
92-0071	98-0108	IR51HD224	IRFR1205TRR	IRK2085S-01
92-0094	98-0119	IR53H320	IRFR120ZTR	IRK2085S-02
92-0101	98-0126	IR53H420	IRFR12N25DTR	IRK2085S-03
92-0112	98-0140	IRF1302L	IRFR13N15DTRL	IRK2085S-04
92-0115	98-0143	IRF1404ZL-309P	IRFR13N15DTRR	IRL1004
92-0120	98-0147	IRF1405ZSTRL-7P	IRFR2307ZTRL	IRL1004STRL
92-0129	98-0148	IRF1503L	IRFR2407TRR	IRL2505-019
92-0151	98-0163	IRF2204L	IRFR3504	IRL2703STRL
92-0159	98-0165	IRF2804L-7P	IRFR3504ZTR	IRL3103D1SPBF
92-0160	98-0169	IRF2805	IRFR3505TRR	IRL3103D1STRLP
92-0176	98-0198	IRF2907ZSTRL	IRFR3704TRL	IRL3202STRLPBPF
92-0183	98-0199	IRF3007L	IRFR3704TRR	IRL3402S
92-0184	98-0200	IRF3007S	IRFR3704ZTRR	IRL3402STRL
92-0219	98-0201	IRF3515L-103	IRFR3706TRL	IRL3502STRR
92-0221	98-0203	IRF3515STRR	IRFR3707ZCTRLP	IRL3714STRR
92-0222	98-0208	IRF3704Z	IRFR3707ZTRR	IRL3714ZL
92-0243	98-0216	IRF3704ZCL	IRFR3711TRR	IRL3715STRL
92-0247	98-0217	IRF3704ZSTRL	IRFR3711ZTRR	IRL3715ZCS
92-0249	98-0236	IRF3704ZSTRR	IRFR9N20DTRL	IRL3715ZCSTRL
92-0251	98-0254	IRF3709STRL	IRFS17N20DTRR	IRL3715ZL
92-0252	98-0266	IRF3711ZCSTRL	IRFS3307TRL	IRL3715ZS
92-0255	98-0273	IRF3711ZCSTRR	IRFS33N15DTRL	IRL3715ZSTRL
92-0256	98-0274	IRF3711ZS	IRFU2607Z	IRL3715ZSTRR
92-0257	98-0275	IRF3711ZSTRL	IRFU3505	IRL7833L
92-0314	98-0286	IRF3711ZSTRR	IRFU3707Z-701	IRL7833STRR
94-2034	98-0303	IRF540ZSTRL	IRFU3709Z-701	IRL8113S
94-2101	98-0311A	IRF6215L-103	IRFU3711	IRLBA1304
94-2105	98-0311B	IRF7233TR	IRFU3911	IRLBD59N04EPBF
94-2175	98-0311C	IRF7241TR	IRFZ24V	IRLC024ZB
94-2183	98-0311D	IRF7325TR	IRFZ24VL	IRLC2402B



# International Rectifier

41915 Business Park Drive, Temecula, California 92590 \* Telephone (951) 676-7500

94-2223	98-0311E	IRF7339D1	IRFZ44VSTRL	IRLC2502B
94-2231	98-0311F	IRF7339D1TR	IRFZ44VSTRR	IRLC2910BV
94-2242	98-0311G	IRF7350TR	IRFZ48Z	IRLC3713-KD
94-2307	98-0311H	IRF7422D2TR	IRG4BC15UD-STRL	IRLC3714ZB
94-2314	98-0311I	IRF7433TR	IRG4BC20F-SPBF	IRLC3715ZB
94-2321	98-0311J	IRF7451TR	IRG4BC20KD-STRR	IRLC3715ZC
94-2347	98-0311K	IRF7468TR	IRG4BC20K-STRLP	IRLC3715ZCB
94-2375	98-0311L	IRF7484QPBF	IRG4BC20MD	IRLL2703TR
94-2376	98-0311M	IRF7484QTRPBF	IRG4BC20UDSTRLP	IRLR3105TR
94-2377	98-0311N	IRF7490TR	IRG4BC20U-S	IRLR3714TRR
94-2378	98-0311O	IRF7493TR	IRG4BC30FD-STRR	IRLR3715TR
94-2390	98-0311P	IRF7504TR	IRG4BC30KD-005	IRLR3715TRR
94-2437	98-0311Q	IRF7807D2TR	IRG4BC30K-STRR	IRLR7807ZTR
94-2457	98-0334	IRF7807VD2TR	IRG4BC30U-S	IRLR7811WTRL
94-2465	98-0388	IRF7831TR	IRG4BC40U	IRLR7821TRL
94-2798	IP2003	IRF7834TR	IRG4BC40W-L	IRLR7821TRR
94-2997	IP2003TR	IRF7842TR	IRG4C2814SB	IRLR7833TRL
94-3114	IR062HD4C10U-P2	IRF7901D1TR	IRG4CC30KD	IRLR8113TRL
94-3212	IR1167APBF	IRF8915TR	IRG4CC72UB	IRLU3105
94-3235	IR2015S	IRF9910TR	IRG4CC77UB	IRLU3714
94-3242	IR2015STR	IRF9Z24NSTRL	IRG4CC81UB	IRLU3715
94-3330	IR2086STR	IRFC034NBV	IRG4CC88KB	IRLU3915
94-3357	IR2102STR	IRFC046N	IRG4CC88KC	IRLU7833TRL-701
94-3400	IR2108C		IRG4IBC30KD-110	IRU3037CF
94-3430	IR2112C	IRFC048VB	IRG4PC40FD	PVR2300N
94-3586	IR2118C	IRFC1104B	IRG4PC40UD-203	PVT212S
94-3615	IR2125C	IRFC120VB	IRG4PC50UD-E	PVT412LS-T
94-3646	IR2131	IRFC1503	IRG4PC60F-P	

## Effective Dates:

Customer Notice: August 11, 2008  
Last Time Buy: February 11, 2009  
Last Schedule Shipment: August 11, 2009  
Final Return Date: November 11, 2008  
Expiration of Ship & Debit: November 11, 2008

## Alternate or Replacement Product:

Most products are available in lead-free (PBF) versions. Contact your salesperson for details.

Example: IRF8915TR replaced by IRF8915TRPBF



# International Rectifier

41915 Business Park Drive, Temecula, California 92590 \* Telephone (951) 676-7500

## Contact Information:

CONTACT TYPE	NAME	PHONE	EMAIL
PCN Coordinator	John Michaelson	951 375-4432	Jmichae2@irf.com