

## Product/Process Change Notifications



# PCN - 19 043

Amphenol Information Communication and Commercial Products Group  
[www.amphenol-icc.com](http://www.amphenol-icc.com)

Release Date: June 21 2019

|                                    |  |   |      |
|------------------------------------|--|---|------|
| <b>Product Name:</b>               | Airmax guide modules   |   |      |
|                                    | Airmax connector assessories   |   |      |
| <b>Product Manager:</b>            | Chris Liu  |   |      |
| <b>Subject:</b>                    | Notification of Planned Change   |   |      |
| <b>Distribution:</b>               | Affected customers   |   |      |
| <b>Type of Change:</b>             | Location Change  |   |      |
| <b>Change Description:</b>         | Manufacturing location transfer from Singapore to China for Airmax connector assessories.  |   |      |
| <b>Reason for Change:</b>          | To provide better delivery performance and enhance business support with primary ownersite Amphenol ICC FCI Dongguan, supplier plans to transfer production from Signapore to China site which is closer to AICC FCI Dongguan. |   |      |
| <b>Affected Parts:</b>             | See attached "affected PN list"  |   |      |
| <b>Effective Date of Change:</b>   | September 23, 2019   |   |      |
| <b>Last Time Buy Date:</b>         | NA   |   |      |
| <b>Earliest Disty Return Date:</b> | NA   |   |      |
| <b>Last Time Shipment Date</b>     | NA   |   |      |
| <b>Datasheet Attached?</b>         | NA   |   |      |
| <b>Qual/Test Data Attached?</b>    | NA   |   |      |
| <b>Samples Availability Date:</b>  | July   | 1 | 2019 |
| <b>Available Alternatives?</b>     | N/A  |   |      |
| <b>Questions?</b>                  | <i>Contact your local AICC Representative, or Product Manager</i>  |   |      |
|                                    | <a href="#">Chris Liu /Product Manager</a>   |   |      |
|                                    | 8866 9210/ <a href="mailto:Chris.Liu@fci.com">Chris.Liu@fci.com</a>  |   |      |

Note:  
 Customers should contact Product Manager (or their local AICC Representative) directly regarding any concern on the PCN.  
 Lack of any such customer feedback within three weeks of PCN release date will be interpreted as non-objection .

| PCN Reference | MPN            | Change          |
|---------------|----------------|-----------------|
| PCN19043      | 10037908-101LF | LOCATION CHANGE |
| PCN19043      | 10037908-102LF | LOCATION CHANGE |
| PCN19043      | 10037908-103LF | LOCATION CHANGE |
| PCN19043      | 10037908-104LF | LOCATION CHANGE |
| PCN19043      | 10037908-105LF | LOCATION CHANGE |
| PCN19043      | 10037909-101LF | LOCATION CHANGE |
| PCN19043      | 10037910-101LF | LOCATION CHANGE |
| PCN19043      | 10037910-102LF | LOCATION CHANGE |
| PCN19043      | 10037910-103LF | LOCATION CHANGE |
| PCN19043      | 10037910-104LF | LOCATION CHANGE |
| PCN19043      | 10037910-105LF | LOCATION CHANGE |
| PCN19043      | 10037911-101LF | LOCATION CHANGE |
| PCN19043      | 10037911-102LF | LOCATION CHANGE |
| PCN19043      | 10037911-103LF | LOCATION CHANGE |
| PCN19043      | 10037911-104LF | LOCATION CHANGE |
| PCN19043      | 10037912-101LF | LOCATION CHANGE |
| PCN19043      | 10037912-102LF | LOCATION CHANGE |
| PCN19043      | 10037912-103LF | LOCATION CHANGE |
| PCN19043      | 10037912-104LF | LOCATION CHANGE |
| PCN19043      | 10037912-105LF | LOCATION CHANGE |
| PCN19043      | 10037912-106LF | LOCATION CHANGE |
| PCN19043      | 10037912-107LF | LOCATION CHANGE |
| PCN19043      | 10037912-108LF | LOCATION CHANGE |
| PCN19043      | 10037912-109LF | LOCATION CHANGE |
| PCN19043      | 10037912-111LF | LOCATION CHANGE |
| PCN19043      | 10037912-112LF | LOCATION CHANGE |
| PCN19043      | 10037912-113LF | LOCATION CHANGE |
| PCN19043      | 10037912-114LF | LOCATION CHANGE |
| PCN19043      | 10037912-115LF | LOCATION CHANGE |
| PCN19043      | 10037912-116LF | LOCATION CHANGE |
| PCN19043      | 10037912-117LF | LOCATION CHANGE |
| PCN19043      | 10037912-118LF | LOCATION CHANGE |
| PCN19043      | 10037912-119LF | LOCATION CHANGE |
| PCN19043      | 10037915-101LF | LOCATION CHANGE |
| PCN19043      | 10044314-101LF | LOCATION CHANGE |
| PCN19043      | 10044366-101LF | LOCATION CHANGE |
| PCN19043      | 10044366-102LF | LOCATION CHANGE |
| PCN19043      | 10044366-103LF | LOCATION CHANGE |
| PCN19043      | 10044366-104LF | LOCATION CHANGE |
| PCN19043      | 10044366-105LF | LOCATION CHANGE |
| PCN19043      | 10044366-106LF | LOCATION CHANGE |
| PCN19043      | 10044366-107LF | LOCATION CHANGE |
| PCN19043      | 10044366-108LF | LOCATION CHANGE |
| PCN19043      | 10045367-101LF | LOCATION CHANGE |
| PCN19043      | 10045368-101LF | LOCATION CHANGE |

|               |                |                 |
|---------------|----------------|-----------------|
| PCN19043      | 10045368-102LF | LOCATION CHANGE |
| PCN19043      | 10045368-103LF | LOCATION CHANGE |
| PCN19043      | 10045368-104LF | LOCATION CHANGE |
| PCN19043      | 10045368-105LF | LOCATION CHANGE |
| PCN19043      | 10045509-101LF | LOCATION CHANGE |
| PCN19043      | 10045509-102LF | LOCATION CHANGE |
| PCN19043      | 10045509-103LF | LOCATION CHANGE |
| PCN19043      | 10045509-104LF | LOCATION CHANGE |
| PCN19043      | 10045509-105LF | LOCATION CHANGE |
| PCN19043      | 10045509-106LF | LOCATION CHANGE |
| PCN19043      | 10045509-107LF | LOCATION CHANGE |
| PCN19043      | 10045509-108LF | LOCATION CHANGE |
| PCN19043      | 10045588-101LF | LOCATION CHANGE |
| PCN19043      | 10045597-101LF | LOCATION CHANGE |
| PCN19043      | 10045597-102LF | LOCATION CHANGE |
| PCN19043      | 10045597-103LF | LOCATION CHANGE |
| PCN19043      | 10045597-104LF | LOCATION CHANGE |
| PCN19043      | 10045597-105LF | LOCATION CHANGE |
| PCN19043      | 10045597-106LF | LOCATION CHANGE |
| PCN19043      | 10045597-107LF | LOCATION CHANGE |
| PCN19043      | 10045597-108LF | LOCATION CHANGE |
| PCN19043      | 10045597-109LF | LOCATION CHANGE |
| PCN19043      | 10045597-111LF | LOCATION CHANGE |
| PCN19043      | 10045597-112LF | LOCATION CHANGE |
| PCN19043      | 10045597-113LF | LOCATION CHANGE |
| PCN19043      | 10045597-114LF | LOCATION CHANGE |
| PCN19043      | 10045597-115LF | LOCATION CHANGE |
| PCN19043      | 10045597-119LF | LOCATION CHANGE |
| PCN19043      | 10063141-101LF | LOCATION CHANGE |
| PCN19043      | 10066832-101LF | LOCATION CHANGE |
| PCN19043      | 10070288-104LF | LOCATION CHANGE |
| PCN19043      | 10084589-101LF | LOCATION CHANGE |
| PCN19043      | 10084589-111LF | LOCATION CHANGE |
| PCN19043      | 10084590-101LF | LOCATION CHANGE |
| PCN19043      | 10084609-101LF | LOCATION CHANGE |
| PCN19043      | 10084609-111LF | LOCATION CHANGE |
| PCN19043      | 10084610-101LF | LOCATION CHANGE |
| PCN19043      | 10088275-101LF | LOCATION CHANGE |
| PCN19043      | 10101902-101LF | LOCATION CHANGE |
| PCN19043      | 10120051-101LF | LOCATION CHANGE |
| PCN19043      | 10149607-101LF | LOCATION CHANGE |
| <b>Count:</b> | <b>86</b>      |                 |